

[Forum Home](#) > [OKA Maintenance](#) > One to watch

[Outback Jack](#)

Member

Posts: 381

The old girl has spent much of its life on corrugated dirt roads. So it has a little bit more wear in places.

However I wasnt expecting this.



**Clutch Cable has rubbed through chassis**

--

**October 3, 2012 at 1:09 PM**

[joseph baz](#)

Member

Posts: 331

You will probably find that the coating of mud and crap on the cable work as an abrasive, the rule in my book is nothing should be loose for more than 300 mm.....I looove cable ties, good

time to inject some fish oil inside the chassis  
Cheers,joe

**October 3, 2012 at 7:33 PM**

[Outback Jack](#)

Member

Posts: 381

Was looking a little more today.

Funny you can see things 100 times and still miss it.

I noticed that the cab mounting brackets had cracked.

But didnt notice this

**RHS AEON RUBBER MOUNT**



As compared to

**LHS AEON RUBBER MOUNT**



Must have take one hell of a bump to bend that.....

--

October 3, 2012 at 8:36 PM